

RELEASE NOTES

Solidigm™ Storage Tool - GUI

March 2024





Solidigm may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Solidigm reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

Solidigm disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Contact your Solidigm representative or your distributor to obtain the latest specifications and before placing your product order.

For copies of this document, documents that are referenced within, or other Solidigm literature, please contact your Solidigm representative.

All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice.

© Solidigm. Solidigm and the Solidigm logo are trademarks of Solidigm in the United States and other countries. Other names and brands may be claimed as the property of others.



Revision History

| Revision | Software Revision | Description | Date |
|----------|----------------------|---|-------------------|
| 001 | 1.0 | This is the first revision of the Solidigm™ Storage Tool (SST). This version of the tool contains below fixes; and the functionality of many current tools, see the User Guide for more information, with support for Intel® / Solidigm™ client and data center SSD. | March 2022 |
| 002 | 1.1 | This version of the tool contains following changes: This revision adds a firmware update for 670p, 665p, 660p, 760p, Pro 7600p, Pro 6000p, E6100p P3100 and P4101. CVE document update (see Solidigm Advisory SOLIDIGM-SA-00563) | May 2022 |
| 003 | 1.1 | Documentation Correction | May 2022 |
| 004 | 1.2 | Firmware update for D7-P5510, D5-P5316, D3-S4520 / S4620 | July 2022 |
| 005 | 1.3 | This version of the tool contains following changes: Firmware update for D3-S4510 / S4610 Added HMC feature support for P41 Plus Various bug fixes and small enhancements | September 2022 |
| 006 | 1.4 | This version of the tool contains following changes: Added ability for workload tracker Ended ESXi 6.x support due to the end of support from VMWare Various bug fixes and small enhancements | December 2022 |
| 007 | 1.5 | This version of the tool contains following changes: Firmware update for D3-S4510 / S4610 Various bug fixes and small enhancements | January 2023 |



| 008 | 1.6 | This version of the tool contains following changes: Firmware update for P41 Plus Added CSV File Type export on GUI for Data extraction | February 2023 |
|-----|------|---|----------------|
| 009 | 1.7 | This version of the tool contains following changes: Firmware update for D3-S4520 / S4620 and D7-P5520 / P5620 Added ability to bypass full system device scan when user provides device path Fixed some SST command issues on Microsoft NVMe Inbox Driver Various bug fixes and small enhancements | March 2023 |
| 010 | 1.8 | This version of the tool contains following changes: Fixed the issue of certain drives not showing drive temperature | May 2023 |
| 011 | 1.9 | This version of the tool contains following changes: Firmware update for D3-S4510 / S4610, D5-P5316 and D5-P5430 Various bug fixes and small enhancements | July 2023 |
| 012 | 1.10 | This version of the tool contains following changes: Firmware update for D7-P5510 Various bug fixes and small enhancements | September 2023 |
| 013 | 1.11 | This version of the tool contains following changes: Firmware update for selected D7-P5510 drives Firmware update for P5520/P5620 Firmware update for S4520/S4620 Updated LSI MegaRAID library for newer cards support | December 2023 |
| 014 | 1.12 | This version of the tool contains following changes: Firmware update for selected D7-P5810 Fix for firmware update not available for few D7-P4511 models Fixed issue of devices enumerating as SCSI in RHEL 7 Added support for new models for various products Various small bug fixes and enhancements | March 2024 |

Note: If you purchased your Intel® / Solidigm™ SSD from an OEM, your firmware version may have a different naming sequence. Contact your local OEM representative for the latest firmware revisions.



Solidigm Data Center SSD Products Revision History

1 Solidigm™ D7-P5810

| Date | Revision | Description |
|------------|----------|--|
| March 2024 | 1CV10200 | Mitigates the following issues besides some other minor/corner case fixes: |

2 Solidigm™ D7-P5520 / P5620 (formerly Intel®)

| Date | Revision | Description |
|---------------|----------|---|
| December 2023 | 9CV10450 | Mitigates the following issues besides some other minor/corner case fixes: NVMe-MI Basic Throttle State Value May Persist After Exiting Throttling State Power Management Set Feature Command sent Over NVMe MI Causes Drive to go into Disable Logical Mode Vendor Unique Feature Identifier C6h Not Reflecting Power Mode Setting Changes Made with Feature Identifier 02h Drive May Fail to enumerate During Drive Boot Up Sequence PCIe Link up Sequence May Fail During AC/DC Cycle |
| March 2023 | 9CV10410 | Mitigates the following issues besides some other minor/corner case fixes: Non-Graceful Shutdown Counter Not Incrementing During Unsafe Shutdowns within DEh Log Page UEFI Driver Health Status GetHealthStatus Returning Unsupported PCIe Unsupported Request Errors Observed by Host during Drive Power Cycle Drive De-Enumeration During PCIe Link Up Sequence Intermittent Failure During Drive Boot Sequence Causes No Drive Attached Incorrect NVMe MI Response Message Status During Drive's Time to Ready |

3 Solidigm™ D7-P5510 (formerly Intel®)

| Date | Revision | Description |
|---------------|----------|---|
| December 2023 | JCV10404 | Mitigates the following issues besides some other minor/corner case fixes: Allow the Opal drive to undergo an MR3 update without the drive becoming locked Adjustments to wear levelling mechanism Mitigate issue that cause drive to return last data written to NAND |



| September 2023 | JCV10400 | Mon-OPAL drives only: Mitigates the following issues besides some other minor/corner case fixes: Environment that does not Implement Required Command Ordering Enforcement may cause drive to return last data written to NAND Drive may encounter bad_ctx 3014 due to wear leveling |
|----------------|----------|---|
| July 2022 | JCV10300 | NAND Read Disturb Impact Due to Unique NAND Background Activity Fix BM459 Assert No Available Band/Erase Block Fix Other various fixes and improvements |

4 Solidigm™ D5-P5430

| Date | Revision | Description |
|-----------|----------|--|
| July 2023 | 6CV10110 | Mitigates the following issues besides some other minor/corner case fixes: Environment that does not Implement Required Command Ordering Enforcement may cause drive to return last data written to NAND Host OS fails to boot with the Vendor Defined Firmware option |

5 Solidigm[™] D5-P5316 (formerly Intel®)

| Date | Revision | Description |
|-----------|----------|--|
| July 2023 | ACV10340 | Mitigates the following issues besides some other minor/corner case fixes: Environment that does not Implement Required Command Ordering Enforcement may cause drive to return last data written to NAND PCIe unsupported request errors observed by host during drive power cycle |
| July 2022 | ACV10310 | Add additional support for OPAL 2.0, NVMe 1.4c, NVMe-MI 1.1c, and OCP 0xC0 Log Page |

6 Solidigm[™] D3-S4520 / S4620 (formerly Intel®)

| Date | Revision | Description |
|---------------|----------|--|
| December 2023 | 7CV10130 | Mitigates the following issues besides some other minor/corner case fixes: SMART return status 2CF4H, and SMART attribute AFh and EBh = 1 after ~2 years storage without power, indicating PLI capacitor test failure (U.2 FF only) Drive did not correctly throttle when end of life defect threshold was reached |



o Unable to format and possible de-enumeration during installing image operation containing crypto scramble command

| March 2023 | 7CV10120 | Mitigates the following issues besides some other minor/corner case fixes: SMART attribute AFh and EBh was going to 1 after ~2years of storage without power, when the PLI capacitor was in fact healthy A non-warranty SMART attribute C5h (pending sector count) was increasing in a corner case scenario |
|------------|----------|--|
| July 2022 | 7CV10111 | Mitigates the following issues besides some other minor/corner case fixes: Command timeouts CI054, sometimes followed by ASSERT_SR002 and The SATA link going down. AFh Smart attribute accidentally drops from 100 to 1 upon power on or power cycle. False failure of the cap test. However, nothing is/was wrong with the capacitor. SMART attribute B7h SATA downshift counter not updating accurately when a SATA downshift occurs. SSD warm reboot issue in RAID mode: BIOS hangs and drive not enumerating after OS install and warm reset in RAID mode |

7 Solidigm™ D3-S4510 / S4610 (formerly Intel®)

| Date | Revision | Description |
|----------------|-----------------------------------|--|
| July 2023 | XCV10165 (2.5") | Follow up fix for SMART attributes (AFh, EBh) incorrectly triggered after long-term storage (Only 2.5" SKUs are impacted) SMART return status fix |
| January 2023 | XCV10160 (2.5") | Mitigates the following issues: • SMART attributes (AFh, EBh) incorrectly triggered after long-term storage (Only 2.5" SKUs are impacted) |
| September 2022 | XC311151 (M.2) XCV10151 (2.5") | Mitigates the following issues: Occasional IO timeout under heavy workloads potentially leading to drive drops |

8 Solidigm[™] DC P3100 (formerly Intel®)

| Date | Revision | Description |
|----------|----------|---|
| May 2022 | 119D | Mitigates security vulnerability (see Solidigm Advisory <u>SOLIDIGM-SA-00563</u>) |



9 Solidigm™ DC P4101 (formerly Intel®)

| Date | Revision | Description |
|----------|----------|--|
| May 2022 | 009D | Mitigates security vulnerability (see Solidigm Advisory <u>SOLIDIGM-SA-00563</u>) |

Solidigm Client SSD Products Revision History

1. Solidigm™ P41 Plus

| Date | Revision | Description |
|---------------|----------|---|
| February 2023 | 002C | Fixes possible early disablement of DSLC Fixes SMART Health info corruption and NDA that occasionally occur due to unexpected power loss Improves drive power on to ready time during certain rebuild conditions after unexpected power loss Corrects Verify Command missing in NVMe Commands Supported and Effects Log as reported by drive Fixes occasional drive hang experienced during OS imaging process in WinPE environment |

2. Solidigm[™] 660p (formerly Intel®)

| Date | Revision | Description |
|----------|----------|---|
| May 2022 | 005C | Potential BSOD during Power State Transition Mitigates security vulnerability (see Solidigm Advisory <u>SOLIDIGM-SA-00563</u>) |

3. Solidigm[™] 665p (formerly Intel®)

| Date | Revision | Description |
|----------|----------|---|
| May 2022 | 002C | Mitigates security vulnerability (see Solidigm Advisory <u>SOLIDIGM-SA-00563</u>) |



4. Solidigm[™] 670p (formerly Intel®)

| Date | Revision | Description |
|----------|----------|---|
| May 2022 | 003C | Fix to thermal throttling Flow Fix for Null pointers Block SID Fix |
| | | Mitigates security vulnerability (see Solidigm Advisory <u>SOLIDIGM-SA-00563</u>) |

5. Solidigm[™] 760p (formerly Intel®)

| Date | Revision | Description |
|----------|----------|---|
| May 2022 | 006C | Mitigates security vulnerability (see Solidigm Advisory <u>SOLIDIGM-SA-00563</u>) |

6. Solidigm™ Pro 7600p (formerly Intel®)

| Date | Revision | Description |
|----------|----------|---|
| May 2022 | 006P | Mitigates security vulnerability (see Solidigm Advisory <u>SOLIDIGM-SA-00563</u>) |

7. Solidigm™ Pro 6000p (formerly Intel®)

| Date | Revision | Description |
|----------|----------|---|
| May 2022 | 132P | Mitigates security vulnerability (see Solidigm Advisory <u>SOLIDIGM-SA-00563</u>) |

Solidigm Other SSD Products Revision History

1. Solidigm™ E 6100p (formerly Intel®)

| Date | Revision | Description |
|----------|----------|---|
| May 2022 | 006E | Mitigates security vulnerability (see Solidigm Advisory <u>SOLIDIGM-SA-00563</u>) |



§



List of Solidigm SSD Products

Please check all supported Solidigm™ SSDs (formerly Intel®) in the following link:

https://www.solidigm.com/us/en/support-page/product-doc-cert/ka-00099.html

§